


F I A N C O 1


Errore passo cummulativo



Fp : 0.0036
Tol.: 0.0100

Ele.:PitchRackEval


Errore passo singolo



fp : 0.0018
Tol.: 0.0100
fu : 0.0030
Tol.: 0.0100

F I A N C O 2


Errore passo cummulativo



Fp : 0.0083
Tol.: 0.0100

Ele.:PitchRackEva2

Errore passo singolo



fp : 0.0026
Tol.: 0.0100
fu : 0.0021
Tol.: 0.0100



MESSTECHNIK
WETZLAR GmbH
Metrology Systems


Controllo Cremagliera

Passo assiale : 3.3430
Angolo pressione: 20.0000
Angolo inclinaz.: 20.0000

Denom:
Dis. :
Oper.:AMAVROV
Data :15-FEB-20 10:35
Nota :
Units:mm


Profilo vano

Vano1




19.55.34 19.58.19

Vano2



19.56.31 20.01.46


Vano3



19.57.31 20.00.30


Inclinazione vano

Vano1




20.00.25 19.58.15

Vano2



20.01.24 20.02.00

Vano3



20.00.50 20.01.57



MESSTECHNIK
WETZLAR GmbH
Metrology Systems

Controllo Cremagliera

Passo assiale : 3.3430
Angolo pressione: 20.0000
Angolo inclinaz.: 20.0000